

APPENDIX

GEOTEXTILE TEST METHODS SUMMARY ASTM Committee D35

<u>DESIGNATION</u>	<u>TEST METHOD</u>
ASTM D 1117	Standard Test Method of Testing Non-Woven Fabrics
ASTM D 1683	Standard Test Method for Failure in Sewn Seams of Woven Fabrics
ASTM D 4354	Standard Practice for Sampling of Geotextiles for Testing
ASTM D 4355	Standard Test Method for Deterioration of Geotextiles From Exposure to Ultraviolet Light and Water (Xenon-Arc Type Apparatus)
ASTM D 4439	Standard Terminology for Geotextiles
ASTM D 4491	Water Permeability of Geotextiles by Permittivity
ASTM D 4533	Standard Test Method for Trapezoid Tearing Strength of Geotextiles
ASTM D 4595	Standard Test Method for Tensile Properties of Geotextiles by the Wide-Width Strip Method
ASTM D 4632	Standard Test Method for Breaking Load and Elongation of Geotextiles (Grab Method)
ASTM D 4751	Standard Test Method of Determining Apparent Opening Size of Geotextiles
ASTM D 4759	Standard Practice of Determining for Specification Conformance of Geosynthetics
ASTM D 4833	Index Puncture Resistance of Geotextiles
ASTM D 4873	Identification, Storage, and Handling of Geotextiles
ASTM D 4884	Wide Width Seam Testing
ASTM D 4886	Abrasion Using the Sliding Block